

The responses to bidders' inquiries are provided for the bidders' convenience only. In some instances, the question and answer may represent a summary of the matters discussed rather than a word-for-word recitation. The responses may be considered along with all other information furnished to prospective bidders for the purpose of bidding on the project. The availability or use of information provided in the responses to contractors' inquiries is not to be construed in any way as a waiver of the provisions of Section 2-1.03 of the Standard Specifications or any other provision of the contract, the plans, Standard Specifications or Special Provisions, nor to excuse the contractor from full compliance with those contract requirements. Bidders are cautioned that subsequent responses or contract addenda may affect or vary a response previously given. Inquiries along with responses may be posted at the website only when the inquiries are submitted in any of the acceptable manner prescribed under the Notice to the Contractors and when the responses have already been communicated to the individual inquirers. Bidders' inquiries received over the phone must be followed-up and submitted in writing for an official response.

The Bidders' inquiries and Responses may be updated from time to time and bidders are enjoined to check the website regularly and immediately prior to the scheduled bid opening.

Caltrans District 8 Office is located at 464 W. Fourth Street, San Bernardino, CA 92401-1400.

Send Contractor Inquiries via email to d8_pbi@dot.ca.gov

The mailing address is 655 2nd Street, San Bernardino, CA 92402.

Phone (909) 383-5961

Fax (909) 383-6739.

All inquiries must include the contract number.

08-A1860	
Inquiry No.	Inquiry/Response
1.0	<p>Question_1:item 9 calls for 5000 lf on bid schedule, sheet Q-1 calls for 7200 lf however the job site has over 12,000 lf please advise,</p> <p>Response: Bid Schedule (see Contract Sheet 70 of 409) quantities are correct.</p> <p>Sheet Q-1 has typographical errors (see 0M230_Quantities.pdf)</p> <ul style="list-style-type: none"> - Remove Chain Link Fence R30.0/R31.0 is 3100 - Remove Chain Link Fence TOTAL is 5000 - Place Chain Link Fence (Type CL-6) (FT) is 3100 - Place Chain Link Fence TOTAL is 5000
2.0	<p>Question_2:Starting at mile marker 28.9 heading North approximately 500 ft, the fence parallels along a concrete lined ditch, Will this fence be reduced? Or can we start North of the ditch? The fence seems to be in great shape along the ditch and removing it could cause a great deal of erosion to fall down into the ditch.</p> <p>Response: Per Sheet X-1, "EXACT LIMITS SHALL BE DETERMINED BY THE ENGINEER."</p>